

Hyper Terminal in Windows 7.

PURPOSE:

Hyper Terminal is a very useful tool to test communications between your PC and other serial and network devices. However Microsoft Windows 7 does not include this tool anymore. This document will show where to put the correct files to make the old hyper terminal work on a Windows 7 PC.

INSTRUCTIONS:

1. Copy the following files to C:\Program Files\Windows NT
dialer.exe
htrn_jis.dll
hypertrm.exe
2. Copy the following files to C:\WINDOWS\Help
hypertrm.chm
hypertrm.hlp
3. Copy the following files to C:\WINDOWS\system32
hypertrm.dll
4. Right click on hypertrm.exe from the C:\Program Files\Windows NT directory and select Create Shortcut.
5. Cut and paste this shortcut from its current location to a more useful location like the desktop.
6. Double click on the shortcut to run Hyper Terminal.